All measurements are in inches. Not to scale! Pretty close. Please pardon the shaky free hand side (left) For left curve, measure and connect the dots. Column B is inches from bottom Column C is inches from right side В С 12 5 3/8 1/2 0 6 1/4 11.5 11 2 3/8 3/8 10 7 0 9 7 3/4 9 11/16 8 8 3/8 13 7/8 7 8 7/8 6 9 1/4 7 5/16 5 9 1/2 4 9 3/4 3 9 3/4 2 9 1/4 0 8 5/8 1 3/4 1 1/2 7 5/8

5 -